APPENDIX A

APPENDIX TO AN ORDER OF THE KENTUCKY PUBLIC SERVICE COMMISSION IN CASE NO. 2004-00189 DATED JUNE 25, 2004

270-821-4288- ω 270-383-3275- H

RECEIVED

Of 7 plus photo

APR 2 9 2004

PSC Consumer Services

COMMONWEALTH OF KENTUCKY

BEFORE THE PUBLIC SERVICE COMMISSION RECEIVED

In the matter	of: AFR 2 9 2004
John /	Tithur Yarbrough } COMMISSION
•	COMPLAINANT)
vs. Ker	itucky Utilities .
	DEFENDANT)
The complai	nt of John Authur Yanbround respectfully shows: (Your Full Name)
(a)	John Arthur Yarbrough From Full Name) 1575 ILSLEY Rd Madisonible Ky 42431
(b)	(Your Address) Kentucky Utilities (Name of Utility) Earlington Kentucky (Address of Utility)
(c)	That: See additional page (Describe here, attaching additional sheets if necessary.
	the specific act, fully and clearly, or facts that are the reason
	and basis for the comptaint)

Continued on Next Page



John Arthur Yarbrough vs. Kentucky Utilities
Page 2 of 2
Wherefore, complainant asks Replacement costs of: (Specifically state the relief desired.)
JVC-VCR-HR S59004 @25000, JUC-CD-XL F254-200
Yamaha Receiver-CR-2040-85000 Drake Satall fr-1024e 4 Ambico rewinder V0758e4500 repair of TV c 15000
Total 189500
Dated at Madison ville ky, Kentucky, this 28 day (Your City)
of April 2004 (Month)
Your Signature
NUNE (SON)
(Name and address of attorney, if any)

🗽 e sara de curro e reconocio se con la sera e la composició de la compos

COMMONWEALTH OF KENTUCKY
BEFORE THE PUBLIC SERVICE COMMISSION
In the matter of John A. Yarbrough VS. Kentucky Utlities

In approximately the year 2000, K.U. linemen, Laffoon and Brinkley, repaired my electrical service that had been pulled off the wall by a falling limb. They cut and shortened the service wire to my house to lessen the swag and installed a wire-clamp type connector. Un November 29, 2002 this connector let go, that windy night, causing 220 volts to run through my 110 volt outlets damaging my TV and stereo equipment. When I came home all the lights were extra bright, the refrigerator was cycling strangely and there was smoke coming from my stereo. I went outside and checked my electric service but it looked ok. I called an electrician who said it must be a disconnected neutral so I went outside again and pointed a flashlight up at the service and could see that my neutral wire was separated at the wire connector that K.U. had installed. The meter was still connected to the wall and the pipe the wires run through was still vertical. Mr. Utley's report that I have only recently received thanks to your help, despite my own attempts to acquire it. (see enclosed fax) says that my service was torn loose. I have never had a chance to challange this report till now. If his report were accurate, as I understand it, there would have been nothing holding my service to the wall so it would have been pulled horizontal by the weight of the span of wires. This wasn't the case. I am sure the service was still vertical. (see enclosed recent photo, with wrong date setting)

when K.U. came out to repair this, I walked around the yard with lineman, Perry Utley looking for the cause. I thought we were in agreement that the small rotted limb we found, which I remember being no more than four inches in diameter at one end, couldn't have weighed enough to break loose the wire connector since these are supposed to be as strong as the wire itself. If a big enough limb had fallen on the wire, I believe it should have pulled the service and meter as well as the single insulator holding it, off of the wall before breaking. I have a clear memory of going outside, after talking to the electrician on the phone, and pointing a flashlight up at the wiring and seeing that my neutral had become separated at the wire clamp connector. My meter was still connected to the house and the pipe the wires run through was still vertical.

If there is a measured value for the strength of this wire connector, it will surely be enough to pull the insulator holding my service out of my wall, if not enough to pull the whole wall down on my old house. If I had known the wire connector might easily come apart, I would never have accepted the patch. K.U. installed the connector and should be responsible for damage to my equipment due to it's poor performance for whatever reason, whether it was improperly installed or faulty in some way. They should also replace this wire as I asked, with one without a connector before I have more trouble.



I didn't want to turn this in to my insurance company because it might endanger my record. I feel I have been treated unfairly by K.U. and bruched acide by their Risk Management Service. I only recently found out about the Public Service Commission. I have enclosed copies of my correspondence with K.U. and welcome any questions. I appreciate your time. I can be contacted at work at (270) 8214288 phone/fax or at home at (270) 383-3275. I understand there was also supposed to have been some record made of my damage at the time. This wasn't done.





copy

March 20, 2002

Providing Risk Management
Solutions for:
Claims Administration
Workers Compensation
Health Benefits
Excess Insurance
Loss Control
Industrial Hygiene
Professional Liability
Automobile Liability

General Liability

Arthur Yarbrough 1575 Ilsley Road Madisonville, Kentucky 42431

Re: Claim Number:

GL01-04132

D/A:

November 29, 2001

Our Insured:

Kentucky Utilities

Dear Mr. Yarbrough:

This letter is in response to your recent call concerning the above referenced incident and in response to your claim for damages against Kentucky Utilities. We did not have an incident report on your location and incident until the local Kentucky Utilities office completed researching your incident.

Our records show that a tree/limb fell on the transformer and pulled your neutral into which could have caused a surge that would have caused damaged to appliances in your house. The tree/limb falling was the proximate cause of the surge that damaged your equipment. The company exercises reasonable care and diligence in an effort to supply service continuously and without interruption, however, we cannot guarantee continuous service. Kentucky Utilities tariff agreement with the Public Service Commission does not hold Kentucky Utilities liable for damages resulting from interruptions of electrical service not caused by the willful negligence of the Company, or resulting from any cause or circumstance beyond the reasonable control of the company, including trees/limbs that fall. You may have a compensable claim under your Homeowner's insurance. We apologize for the delay in not getting this letter to you any sooner.

We regret that out decision cannot be more favorable to your position; however, we must be guided by the facts of the incident.

Sincerely,

Ann B. Westmeyer, Ale, PCLA, CCLA Risk Management Services Corporation Case Manager

270+746-9077

36.56、19.36.56、19.36、19.44、19.75、19.56、19.56、19.36、19.36、19.46、19.46、19.46、19.56、19.36、19.36、19.36、19.36

LOUISVILLE

P.O. Box 22969 Louisville, KY 40252-0989

BENEFITS DIVISION P.O. Box 221409 Louisville, KY 40252-1409

Thone: (502) 526-5906

Fax: (502) 326-5909

Fax: (502) 412-5921

Toll Free: (800) 372-5402

KROVEN - []

LEXINGTON

P.O. Box 55606 Lexington, KY 40555 Phone: (859) \$43-1716 Fax: (859) \$43-1987 Toll Free: (888) 255-1999

BOWLING GREEN PO. Box 10058

PO. Box 10078 Bowling Green, KY 42102 Phone: (270) 781-8181 rax: (270) 781-3900 Toll Free: (888) 824-1842

A.W on Vacation tel

0 2 --

John Yarbrough Madisonville, Ky 42431 all 3
July, 15 2000 July, 15, 2003 270-383-3275-н

821-4288-W

RISK MANAGEMENT SERVICES CORPORATION Ann B. Westmeyer Case Manager RE: Claim GL01-04132

Dear Ms. Westmeyer

In approximately the year 2000 I had a tree limb fall on my elec. wire to my house. This pulled the meter etc. off of the side of my house. When Laffoon and Brinkley put it back up they cut and installed a wire clamp type repair on the neutral to shorten the wire to lessen the swag.

On Nov. 29, 2001 during a windy period the repair let go disconnecting my neutral and causing voltage problems which damaged my TV and stereo equipment before I got home

I didn't want to turn this in to my insurance because the amount wasn't that high and I asked you for a decision on your liability for this and you responded negatively in your letter on March 20, 2002

I feel you have decided this incorrectly since your letter says you relied on your record of a tree limb having fallen on a transformer (wire ?) The KU lineman named Utley and I walked around the yard and we agreed no limbs had fallen recently. If someone made a record to the contrary I would like to read it. In fact I am asking you for the record you relied on so I can see if it is accurate. I feel that if I had known the shortening of the wire wouldn't hold I wouldn't have accepted it. I also feel this wire should be replaced with an unpatched wire before I get a computer.

Sincerely



"Helping you chart the right course."

August 29, 2003

Providing Risk Management

Solutions for:
Claims Administration
Workers Compensation
Excess Insurance
Loss Control
Industrial Hygiene
Professional Liability
Automobile Liability
General Liability

John Yarbrough 1575 Ilsley Road Madisonville, Kentucky 42431

Claim Number:

GL01-04132

D/A:

November 29, 2001

Our Insured:

Kentucky Utilities

Dear Mr. Yarbrough:

This is in regard to the above referenced incident and in response to your letter of July 2003. We have checked back with KU and gone over all of the details with the manager of your area. He checked again with Perry Utley and we find that the version of the occurrence is essentially the same as what we described to you in our letter of March 20, 2002.

KU records indicate that Mr. Utley and Mr. Brumfield noticed a large dead tree limb lying under the service. They remember the limb to be approximately 4-6 inches in diameter and 6-8 feet long. He remembers telling you at the time that it was most likely the limb that had fallen and torn the service loose. Kentucky Utility does not cut the secondary lines; they are the responsibility of the property owner. KU does trim the primary on a rotation basis. They remember the night as being very stormy and extremely windy. We have Mr. Utley's statement, which is part of our file, and the above information was included in his statement.

I realize that this was not what you wanted to hear but based on the above, we will have to respectfully deny your claim for damages. The splice to the wire did not cause this service to fail. As far as requesting that the wire be replaced with a non-spliced wire, you would have to do that through your local service office. You do/did have a compensible claim with your Homeowner's insurance. Please share this letter and your list with them and have them call me with any questions. We regret that our decision cannot be more favorable to your position; however, we must be guided by the facts of the incident.

Sincerely,

Ann B. Westmeyer AIC, SCLA

Sr. Claims adjuster

Risk Management Services Corporation

LOUISVILLE

P.O. Box 22989 Louisville, KY 40252 0989 Phone: (502) 326-5900 Fax: (502) 326-5909 Fax: (502) 412-5921 Toll Free: (800) 372-5402

LEXINGTON

P.O. Box 55606 Lexington, KY 40555 Phone: (859) 543-1716 Fax: (859) 543-1987 Fon Prec: (868) 255-1292

BOWLING GREEN

P.O. Box 10058 Bowling Green, KY 42102 (100nc: (270) 781-0181 Fax: (270) 781-3908 Toll Free: (888) 824-1842

